Sparsholt Parish Council Meeting on Highways 21 August 2014

What is the Problem?

- 1. Volume of traffic through village rat run.
- 2. Speed of traffic through the village.
- 3. Lack of courtesy of drivers. Lack of respect for pedestrians.
- 4. Congestion in the village at peak times.
- 5. HGV transiting and in Crab Wood.
- 6. Condition of the roads.
- 7. Need to dig out ditches.
- 8. Growth of Sparsholt College and consequential increase in vehicle traffic.
- 9. New housing developments in and around Winchester.
 - Danger points in the village:
 - Moor Court Lane/Woodman Lane
 - Dean lane/Woodman Lane
 - Plough/Watley Lane/Home Lane
 - Woodman Lane/Moor Court Lane
 - Woodman lane/Stockbridge Road (accident spot)
 - Northwood Park/Stockbridge Road
 - School drop off (am and pm)
- 10. 50 mph limit on Stockbridge Road is not enforced.

What do we want as an outcome?

- 1. HCC to deal with traffic in villages as expeditiously as city traffic.
- 2. To preserve and protect the nature of the village.
- 3. To improve, protect and strengthen the safety of residents including riders and horses.
- 4. Delivery of improvements promised by HCC at previous meetings.

What can we do about it?

- 1. Traffic survey to be carried out. We need evidence.
- 2. Priority islands give way to oncoming traffic.
- 3. Remove Woodman Lane/Watley Lane island.
- 4. Lollipop person at school drop off and collect times.
- 5. Replace "Not suitable for HGV" signs with HGV weight limit signs.
- 6. Any solution must accommodate needs of the agricultural community in a rural village.
- 7. 20 mph speed limit in village.
- 8. Fixed speed camera.